ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra

Street ID	Street Name	Significant Landmark
W0256, W0295, W0260, W0291, W0287, W0297, W0293, W	Ambedkar Nagar Slum, NA, Maheshwari Nagar 4th Main Rd, Old Panchayathi Office Rd, Maheshwari Nagar O	NEAR RAJANNA BAKERY SIDE KALYANNAGARA

Segment No.	Total Length (m)
13/S-W0256/S031730	363.21

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	37.66	77.514906	13.049595	77.514565	13.049657	I0283	I0231
2	70.04	77.514037	13.047860	77.514210	13.048470	I0283	W0277
3	20.22	77.515807	13.050038	77.515900	13.050196	I0283	W0299
4	96.64	77.516121	13.049910	77.515256	13.050116	W0260	I0231
5	77.69	77.515108	13.050197	77.514506	13.050574	I0283	I0254
6	60.96	77.515178	13.050488	77.514691	13.050763	I0283	W0279

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
CONSTRUCTION OF RCC DRAINS AT KALYANAGARA BALANCE ROADS AND 5TH 6TH CROSS 2 (EITHER)SIDE NEAR RAJANNA BAKERY SIDE 1ST MAIN 1ST A CROSS EITHER SIDE 2N	4900000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Drain Maintenance	

Tender	Work Details	Job No. / Work Code
Not a Tender	RCC DRAIN WORK	013-17-000001

Work Order No.	Work Order Date	Period of Extention
EE/DD/WO/56/2016-17	02/09/2016	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

0.00

KRIDL

Ph e No. | E-Mail ID

9900333496

Field Inspection Details

Number of Trees

0

Any Other Information

Name

G NAGABHUSHAN

Date of Inspection

26/10/2016

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	26/10/2016	25/11/2016	COMPLETED
EE	DODDAIAH	26/10/2016	25/11/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0256, W0295, W0260, W0291,

AEE	JAYALINGAPPA	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0256, W0295, W0260, W0291,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ